

**SECRET****PRIORITY**

Declassification Review by NGA/DoD

P 012000Z  
 FM NPIC WASHDC  
 TO RUCSC/SAC OFFUTT AFB OMAHA NEB  
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA  
 RUCVAA/2D RTS BARKSDALE AFB LA  
 RUEKDA/DIA WASHDC  
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD  
 RUEPIA/CIA WASHDC  
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF  
 RUWGAA/2AF BARKSDALE AFB LA  
 BT  
 S E C R E T CITE NPIC 4663.

1965 JUN 1 20 22Z  
OUT55869

2 JUN 1965

COPIES RECEIVED		
Cy No.	Office	Act.
1	File	
2	OS	
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
3,4	TID	
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B 122 WAS USED IN MISSION 8019 FLOWN ON 27 MAY 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

## 2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: MINOR STATIC DISCHARGES ARE PRESENT ON BOTH EDGES THROUGHOUT THE FILM. THE OUTBOARD EDGE ALSO CONTAINS INTERMITTENT EDGE FOGGING. A MANUFACTURER'S SPLICE IS POSITIONED WITHIN THE FORMAT OF FRAME 244.

C. 9L SIDE: MINOR STATIC DISCHARGES AND INTERMITTENT EDGE FOGGING ARE PRESENT ON BOTH EDGES. FRAMES 3 TO 86 CONTAIN 2 ROWS OF MINUS DENSITY SPOTS IMMEDIATELY ADJACENT TO THE OUTBOARD EDGES OF THE FORMATS. THE SPOT-TO-SPOT SPACING IS 1.7". FRAMES 258 TO 262, 860 AND 898 ARE DEGRADED BY FOG THAT ENTERS THE FORMATS OVER THE OUTBOARD EDGE OF THE FILM. SIMILAR DEGRADATION IS PRESENT IN FRAMES 879, 880, 862 AND 863 BUT THE FOG ENTERS ACROSS THE INBOARD EDGE OF THE FILM. FRAME 682 CONTAINS A MANUFACTURER'S SPLICE.

D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000 TO 2352.

**SECRET**

GROUP 1  
 Excluded from automatic  
 downgrading and  
 declassification

-2-

E. THERE WERE NO MAJOR CAMERA ~~Mal~~FUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE 25 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

S E C R E T

/END OF MESSAGE/

1